

### **Error code discription**

1. Missing teeth - too weak pickup signal - gap in pckup too large - incorrect trigger signal for firmware
2. Too much teeth - spikes from interference - incorrect trigger signal for firmware
3. Incorrect wiring of pickup positive and negative - incorrect trigger signal for firmware
4. Missing TDC or Home Pulse