


# Gearbox Computer LG3.3 EFI Mag

File Name: Gearbox Wiring Diagram LG3.3 EFI Mag

Harness Required: G05 & G06

Last Changed: 24/04/2008



The TPS must be connected to an EFI system which supplies the 5V and ground signal