
## 2Rotor Full Seq High Imp Injector

<u>Last Changed:</u> 08/06/2021 Harness Required: E33



Note! Primary injectors are at the bottom and

Secondaries are at the top of the Intake Plennum

