



# RPM Sensor Wiring OT01-P1

Last Changed: 08/08/2020

Harness: OT01-P1



## Hall or Optic or Tacho RPM Sensor Tap-In



**Note** that Mercury2 or Orion2 ECU's have a green RPM Output on the P2 connectors. This can be tied to the TCU RPM Input directly. Ensure that both ECU and TCU share the same earth point. TCU Input pulses must be the same as RPM output pulses of the ECU.

Software Settings

Active Sensors

☒ RPM

☒ Speed