


Mercedes 5Speed 722.6

Last Changed: 10/12/2018 Page 1 of 2


Harness Required: MTWX01/2, 2x DB2, CON2



Scroll Down for more info


Gearbox Connector

NB! Harness Plug Pin View



Pin	Harness + Color	Resistance	
		Cold	Hot
1	N/C		
2	Gearbox Line Press	Black/Purple	2.5 - 6.5
3	N/C		
4	Sensors TFT	Green	
5	N/U		
6	R2+	Red	
7	N/C		
8	Gearbox 2-3 Shift	Black/Yellow	2.5 - 6.5
9	Gearbox 3-4 Shift	Black/Orange	2.5 - 6.5
10	Gearbox Shift PS	Black/Brown	2.5 - 6.5
11	Gearbox Lockup	Black/Red	2 - 4
12	Sensors GND	Black	
13	Gearbox 1-2 Shift	Black/White	2.5 - 6.5

Gearbox Speed Sensor



Mercedes 5Speed 722.6


Last Changed: 10/12/2018 Page 2 of 2

Harness Required: MTWX01/2, 2x DB2, CON2

Timing Retard Circuit




LED's




NB: Resistors are required for LED's

Tiptronic Buttons



Reverse light Relay



MAP Switch

